



CadCamSystems

Support Document

POWERSHAPE SHORTCUTS

Did you know there are shortcuts in PowerSHAPE? Using shortcuts can make you more productive by spending less time clicking on icons.

These shortcuts are ways you view the model on the screen.

- CTRL + (0 – 9): Standard views
- F2: View wireframe model
- F3: View shaded model
- F6: Resize to fit

The list below shows the possible key combinations and mouse clicks to perform model movement and selection techniques.

		<u>MOUSE BUTTONS</u>		
		Left	Middle	Right
KEYBOARD	No key	Select object	Rotate mode	Extra menus
	CTRL	Add or remove from selection	Zoom mode	Zoom mode
	SHIFT	Add to selection	Pan mode	Pan mode
	SHIFT + ALT	Rotate around screen X axis	Rotate around screen Y axis	Rotate around screen Z axis

Other common shortcut keys:

- CTRL + J: Blank selected
- CTRL + K: Keep selected
- CTRL + Y: Toggle blanked
- CTRL + L: Unblank all
- CTRL + D: Clear selection
- CTRL + H: Composite curve
- CTRL + T: Automatic surfacing
- CTRL + R: Fillet surface
- CTRL + C: Copy selected
- CTRL + V: Paste